

Conservation

Object ID	1,001,867
Heading	Initial
Entry	Stripped and cleaned. Rotors reversed on pump to allow pump to be positioned in front of the engine.
Entry Date	2014-09-25