

Conservation

Object ID	1,002,204
Heading	Strip
Entry	Strip on arrival revealed the injector and pump to be beyond repair and unfortunately the cylinder has a 6 inch internal split. The intention is to fit a wet liner when time is available.
Entry Date	2014-10-29