

Conservation

Object ID	1,113,555
Heading	On Arrival
Entry	Generally poor external condition with sever pitting to flywheels and pump eccentric badly rusted. Bore seized, pump seized. Internal condition fair.
Entry Date	2016-12-14