

Conservation

Object ID	1,114,867
Heading	IP Timing
Entry	1/32" packing under IP valve rod to correct timing. Engine now running much better. IP and HP rod packings require replacement/adjustment
Entry Date	2019-07-07