

Conservation

Object ID	14
Heading	Cosmetic and Other Work
Entry	Because of the general state, covered in builder rubble etc the engine was cleaned and painted. A frame was built and using components from a beyond repair twin cylinder the engine was built up into a displayable condition. Minor work still needed to fuel system and governor rods.
Entry Date	2004-06-10