

# Conservation

Object ID	1,612
Heading	Initial Inspection
Entry	Big end badly worn. Cylinder head replaced following frost damage, non-original part copied from original. Significant damage to outrigger bearing surface on the crankshaft caused by Stillsons.
Entry Date	2007-04-10