

Conservation

Object ID	1,614
Heading	Head Repair
Entry	Flywheel end is frost damaged around the skull. Head removed and crack ends drilled, welded and sealed with Belzona. Timing end head removed and inspected. Replacement head gaskets made in Klingersil as the originals were not useable.
Entry Date	2007-06-15