

Conservation

Object ID	1,614
Heading	Governor Strip
Entry	Noise from the governor area when running - governor stripped and checked but no obvious wear found. The pump drive eccentric strap had witness marks showing it had been hitting the main bearing cap. The eccentric was moved to give clearance.
Entry Date	2010-04-22