

# Conservation

Object ID	1,625
Heading	Further Work
Entry	Inlet and exhaust valves removed and ground, new water seals fitted on exhaust valves. General sorting of remaining small jobs, missing studs, fuel leak on manifold. Still needed, investigation of possible leak in oil cooler following fresh water found in sump.
Entry Date	2011-10-30