

Conservation

Object ID	1,752
Heading	Dismantling
Entry	Due to water in the sump it was decided to strip the engine to component parts on arrival. Overall condition good with only one part requiring replacement - the bottom governor bearing.
Entry Date	2007-09-10