Conservation

Object ID	2,881
Heading	Initial Inspection
Entry	Appears to be in mechanically good order but missing inlet manifold and carburettor. Also missing crankcase breather cover. Has welded repair to frost crack in the cylinder head.
Entry Date	2008-11-10