

Conservation

Object ID	2,891
Heading	Initial Assessment
Entry	Stripped and cleaned by Dan, the engine and compressor are in excellent mechanical order but the compressor is missing the cylinder head.
Entry Date	2010-05-13