

Conservation

Object ID	2,903
Heading	Maintenance
Entry	Initial strip and check showed excessive clearance and some damage in the big end. This was scraped and shimmed. Little end bearing will require replacement and the engine has excessive bore wear.
Entry Date	2009-03-18