

# Conservation

Object ID	2,918
Heading	EOS 2010
Entry	After permanent installation in Hall 1 the engine had an extended run at the EOS. Both main bearings were too warm after a 2 hour run, outrigger fine. Alignment checked and less than 1/2 a thou so bearings will now require removal and check.
Entry Date	2010-10-15