

Conservation

Object ID	2,919
Heading	Initial Inspection
Entry	Good overall condition, fuel pump needs rebuild
Entry Date	2010-02-25