

# Conservation

Object ID	2,925
Heading	Initial Inspection
Entry	The engine is in good overall condition having been well protected at MK despite being in external storage. The only major problems are a stuck piston and one main bearing top half which will require metalling.
Entry Date	2010-02-07