

Conservation

Object ID	3
Heading	Initial Status
Entry	The engine was rebuilt and returned to running order in June 2003 using parts from a similar oil engine. Bore wear is excessive and the engine will not run on full compression as piston slap is excessive.
Entry Date	2003-05-10