

Conservation

Object ID	3,286
Heading	Inspection/Rebuild
Entry	On arrival this engine was found to have a bent crank. A replacement crank and other parts have been donated and in November 2010 the engine was stripped and rebuilt. The engine was in a poor state internally and still required new rings fitting before it can be run. Now fitted to a Hamworthy compressor on steel skids.
Entry Date	2010-12-02