

# Conservation

Object ID	3,286
Heading	On Arrival
Entry	Missing crankcase fron cover and bent crank on the calibrator side. Calibrator glass missing, decompressor assembly missing.
Entry Date	2010-04-29