

# Conservation

Object ID	3,608
Heading	Initial Strip
Entry	Although in poor looking condition, on stripping the pump was found to be in good order with the exception of one broken piston. A new piston has been fabricated from steel tube and a PTFE little end for display purposes. In the process of being installed in the Petter VD bay in Hall 1
Entry Date	2011-08-27