

Conservation

Object ID	4,087
Heading	Big End Failure
Entry	Blocked big end feed caused failure of the bearing which is now being re-metalled. No damage to the crankshaft and the thrower ring/crank drilling have now been cleaned.
Entry Date	2013-10-21