

Conservation

Object ID	4,135
Heading	Initial Assessment
Entry	Engine pressure washed off and treated with preservative. Control panel recently removed with all pipes and connections cut. Throttle linkages seized and solenoid damaged Canopy requires welding and hinge replacement on all access panels
Entry Date	2013-10-19