

# Conservation

Object ID	4,136
Heading	Initial Assessment
Entry	Engine was in a poor external state on arrival so the decision was taken to strip and inspect. Two elements in the pump (2 and 4)were seized so pump and all ancillaries were removed and rebuilt.
Entry Date	2013-02-12