

Conservation

Object ID	6,003
Heading	Initial Inspection
Entry	Missing all manifolds and both magnetos. Turns over and appears to be in reasonable mechanical condition. No further work required until missing components sources
Entry Date	2015-01-25