

# Conservation

Object ID	712
Heading	Update
Entry	restoration work completed and engine was ready to run. However, on attempting to turn the engine over on full compression, several teeth on the clutch/starting gear disintegrated. We believe this to be a result of immersion in water of part of the gear for a long period. The drum has now gone off site to a specialist for repair.
Entry Date	2012-01-09