

Conservation

Object ID	992,543
Heading	Initial Check
Entry	Initial check after arrival from RRHT. Missing water pump assembly/ No ECU present. No covers on exhaust/inlet. 6" aperture flywheel end, no cover. No attempt made to check if the engine is free as internal condition unknown and lack of blanking plates could have allowed ingress of dirt etc.
Entry Date	2014-09-03