

# Conservation

Object ID	992,546
Heading	Initial Check
Entry	Engine cosmetically good but missing manifolds. Blanks fitted to open ports. No attempt to turn over, internal condition unknown.
Entry Date	2014-09-12