Conservation

Object ID	992,546
Heading	Storage
Entry	Blanks removed and VC-10 sprayed into ports. Engine was not turned over. Condition good, no visible deterioration.