





Objectid	Description	Image	Thumb
1,114,464	NULL		
1,114,464	Cages were difficult to extract with a lot of corrosion		
1,114,464	During rebuild by volunteer David Woolley		

Objectid	Description	Image	Thumb
1,114,464	Journals in good condition	 A photograph showing three main shaft journals (crankshafts) lying horizontally on a wooden pallet. The journals are dark, cylindrical metal components with visible crank webs. They are surrounded by various engine parts, including a large, rusty, circular component on the left and a green component on the right. The background is a concrete floor with some debris.	 A small, square thumbnail image showing a close-up of the journals and surrounding engine parts.
1,114,464	Pistons in reasonable order with little wear	 A photograph showing three pistons lying vertically on a light-colored surface. Each piston consists of a dark, cylindrical crown and a long, thin connecting rod. The pistons are arranged in a row, with the connecting rods pointing towards the left. The crowns show some wear and discoloration.	 A small, square thumbnail image showing a close-up of the pistons and connecting rods.