



Objectid	Description	Image	Thumb
1,114,464	NULL		
1,114,464	Cages were difficult to extract with a lot of corrosion		
1,114,464	During rebuild by volunteer David Woolley		

Objectid	Description	Image	Thumb
1,114,464	Journals in good condition		
1,114,464	Pistons in reasonable order with little wear	