






Objectid	Description	Image	Thumb
1,625			
1,625	Along the cylinder covers at Leatherhead		

Objectid	Description	Image	Thumb
1,625	Cylinder covers of engine No 4 at Leatherhead		
1,625	Dismantling underway at Leatherhead		



Objectid	Description	Image	Thumb
1,625	Engine No 1 after unloading at the museum		
1,625	Gauge end No 4 at Leatherhead		

Objectid	Description	Image	Thumb
1,625	Gauge end of engine No 3 at Leatherhead		

Objectid	Description	Image	Thumb
1,625	Leatherhead interior		
1,625	Leatherhead interior		



Objectid	Description	Image	Thumb
1,625	October 2009		

Objectid	Description	Image	Thumb
1,625	On the way back together, September 2009		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild - July 2008		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild - July 2008		
1,625	Stripped for rebuild - July 2008		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild, camshaft chain wheel- July 2008		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild, heads - July 2008		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild, pistons and rods - July 2008		

Objectid	Description	Image	Thumb
1,625	Stripped for rebuild, valve cages - July 2008		