

Conservation

Object ID	12
Heading	Failure To Start
Entry	Fuel priming pump failure on monthly start day. Replaced pump and ran ok. Pump stripped for inspection, broken brush connection.
Entry Date	2010-09-05