

Conservation

Object ID	12
Heading	HP Starter Pump Failure
Entry	Intermittent start failures finally traced to the starter fuel pump. Replaced with a spare found at Filton when removing the alternator.
Entry Date	2009-10-13