

History Objectid	History Event	Event Date
1,026,658	Stripped for inspection, coil requires replacement and other components beyond repair. Usable oparts removed for stores and shell disposed of.	2018-03-12
1,026,658	Beyond economic repair	2022-07-29